

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

December 4, 2015

Carl Clyde Geneva Rock Products, Inc. P.O. Box 1955 Orem, Utah 84059

Subject: Initial Review of Reclamation Cost Estimate, Geneva Rock Products, Inc., Morgan Facility,

M/029/0008, Morgan County, Utah

Dear Mr. Clyde:

The Division of Oil, Gas and Mining has reviewed the revised reclamation cost estimate for the Morgan Facility which was received November 17, 2015. The attached comments will need to be addressed before the Division can approve the estimate.

Please submit your response to this review by February 1, 2016.

Please contact the lead inspector for this site, Leslie Heppler, at 801-538-5257 or Wayne Western at 801-538-5263 if you have questions about these comments or if you would like to schedule a meeting to discuss them. Thank you for your cooperation in completing this permitting action.

Sincerely,

Paul B. Baker

Minerals Program Manager

PBB: lah: eb Attachment: Review

Brent Sumsion, Clyde Companies (bsumsion@clydeinc.com)

Morgan County

p:\groups\minerals\wp\m029-morgan\m0290008-morganfacility\final\rev1-6998-11192015.docx



INITIAL REVIEW OF MODIFIED NOTICE OF INTENTION TO COMMENCE LARGE MINING OPERATIONS

Geneva Rock Products, Inc. Morgan Facility

M/029/0008 December 2, 2015

R647-4-113 - Surety

| Comment # | Sheet/Page/ Map/Table # | Comments | Initials | Review Action |
|--------------|---|---|----------|------------------|
| 1 | 110.2 Reclamation of roads | Please include costs for road reclamation, such as establishing water bars and scarifying haul roads. | whw | |
| 2 | Reclamation of Impoundments, pits and ponds. | Please include the costs for backfilling the storm water impoundments. | whw | |
| 3 | 110.2 Reclamation of Impoundments, pits and ponds. | Please include the cost to construct the plunge pool and terrace drop channel and other associated structures. | whw | |
| 4 | | What will be done with the safety berms on the benches? | whw | |
| 5 | | Please include a cost for reclaiming the highwalls. If the Division took over the property and not all highwalls were at a 45 degree angle then the Division would have to reduce the angles. | whw | |
| 6 | Omission | Please include the costs of cleaning and removal of the above ground fuel tank. | lah | |
| 7 | Bond Summary sheet | Please correct date in upper right hand corner, and in addition, please update the | lah | |